

ONKYO.

SERVICE BULLETIN
NO:98001-1

LAST REVISED : 99/04/21

DATE : 98/08/03

MODELS : KCY-707

SUBJECT : Change of Microprocessor & Dolby IC

1. IC604(sub microprocessor)

a. CXP84124-139Q (find with service manual)

It has a program mistake. Please work with service bulletin no. 9602 if you use this IC..
Pls find the service information Ref.9602 dated 96/11/13.

b. CX84332-159Q

It is improved from 9/13/97 ship.
You can use it without above modification.

c. CX84332-164Q (SN:1-0447-1)

It is improved from 1/10/98 ship.
You can use it without above modification.

2. IC802 (Dolby IC)

a. BA3442BKS (find with service manual)

The number of PCB a'ssy is 33560 and 33560A.

b. CXA1897Q (SN:1-0374-1) 🖱️

It is improved from 5701726913 of serial number.
The number of PCB a'ssy is 33563.