

January, 1998

# VCR 98-01

Hitachi Home Electronics (America), Inc.  
National Service

VCR  
Page 1 of 1


**MODELS:**

VT-MX211A, VT-MX221A, VT-MX411A, VT-MX421A, VT-MX421AC  
VT-MX424A, VT-FX600A, VT-FX601A

**SUBJECT: VCR DIAGNOSTIC CODES**

The above VCR models *may* exhibit a flashing numeric code (diagnostic code) in the Fluorescent Display of the VCR. This diagnostic code indicates a problem within the VCR mechanics or electronic circuits.

Using the information below, match the flashing FL Diagnostic Code with the appropriate flowchart number in the upper left corner.



Blinking Number Location "CH" 1, 2, 3, 4

